

HISTORY KEPT YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>		ILLINOIS HIGHWAY INFORMATION SYSTEM STRUCTURE INFORMATION AND PROCEDURE MANUAL	
NBIS REQUIRED YES <input type="checkbox"/> NO <input checked="" type="checkbox"/>		ITEM NAME MAINTENANCE REPAIR PRIORITY 2 QUANTITY	ITEM NO. 536 PAGE 1 of 1 EFF. DATE 07/01/02
		ISIS	MMIS
RESPONSIBLE FOR UPDATE	N/A	District Maintenance/Operations	
STRUCTURES	N/A	State	
UPDATE SCREENS	N/A	(7) Proposed	
INQUIRY SCREENS	(9) MMIS Proposed Repair	(9) Proposed	

DESCRIPTION AND PURPOSE OF ITEM

This item indicates the quantity of work of a second priority level that should be budgeted, planned and completed by maintenance this year to accomplish the work identified in Item 530 - Work Code.

Priority #2 work will not be performed until Priority #1 work is completed.

CODE AND SCREEN ENTRY INSTRUCTIONS

A six-digit code, right justified.

Enter the quantity of repairs needed, to the nearest whole unit, in the appropriate spaces.

Leave leading (unused) spaces blank.

Leave blank if not applicable.

EXAMPLE:

The deck has:

- 24 lineal feet of joints that are loose and should be replaced this year because they may cause a serious traffic hazard, and
- 12 lineal feet of joints that are leaking and should be replaced this year because they are causing deterioration of the steel stringers.

Enter:

In Priority 1: 24

In Priority 2: 12